SWING CHECK VALVE REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 09:55 PM

SKU
: 3562

BRAND
: DIXON VALVE

MODEL
: 3091RK2

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Replacement metal seal flapper kit, flapper assembly, yoke, springs, shafts, cover gasket (for 3091MA)
Factory Part Number	3091RK2
Used on	3090 series swing check valves
Weight Lb	1.0010

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us