ALUMINUM QUICK CONNECT CLAMP REPAIR PART



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 01:06 AM

SKU
: 4396

BRAND
: DIXON VALVE

MODEL
: 40398BN

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	4" pipe coupler split gasket
Material	Buna-N / EPDM
Factory Part Number	40398BN
Weight Lb	0.0100

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us