SWING CHECK VALVE REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 08:44 PM

SKU
: 4399

BRAND
: DIXON VALVE

MODEL
: 4040RK2

Safety notes:
The smaller torsion springs will not return the flappers contained in the 4041RK1, 4041RK2, 4042RK1 and 4042RK2 kits to a fully closed position if the valve is mounted vertically or upside down. Ensure that these mounting positions are avoided if the smaller springs are used with the 4041RK1, 4041RK2, 4042RK1 and 4042RK2 kits.
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	Complete rebuild kit, white EPDM flapper assembly, yoke, springs, shafts, cover gasket, bolts and lock washers (for 4040RD and 4040TE)
Factory Part Number	4040RK2
Used on	4040 series swing check valves
Weight Lb	1.3400

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us