API COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 06:27 PM

SKU
: 27163

BRAND
: DIXON VALVE

MODEL
: 5354K19

Features:
Poppet, bent link, link pin, link washer, hitch pin, drive link, shaft outside washer, shaft inside washer, shaft cotter pin
Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Valve assembly repair kit
Factory Part Number	5354K19
Used on	5300, 5300B, 5300G, 5400, 5400B & 5400G API couplers
Weight Lb	0.0100

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us