API COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 06:09 PM

SKU
: 27166

BRAND
: DIXON VALVE

MODEL
: 5354K23

Features:
Poppet, bent link, link pin, link washer, 304SS cotter pin, drive link, shaft cotter pin, shaft outside washer, shaft inside washer
Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Poppet Assembly replacement kit
Factory Part Number	5354K23
Used on	5300, 5300BC, 5300BCL

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us