API COUPLER REPAIR KIT

DATE
: 11/23/2026 06:04 PM

SKU
: 27167

BRAND
: DIXON VALVE

MODEL
: 5354K25



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

Features:
Washer, cotter pin, handle (aluminum), shaft outside washer, clevis pin
Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Aluminum handle kit replacement
Factory Part Number	5354K25
Weight Lb	1.4100

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us