API COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 06:05 PM

SKU
: 27174

BRAND
: DIXON VALVE

MODEL
: 5354K5

Features:
O-ring 2-220 (FKM-GFLT), O-ring 212 (FKM-GFLT), shaft outside washer, shaft inside washer, shaft cotter pin
Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	FKM-GFLT shaft seal kit
Factory Part Number	5354K5
Used on	5300G & 5400G API couplers
Weight Lb	0.0290

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us