5500-SERIES API COUPLER REPAIR KIT



DATE
: 11/23/2026 08:32 PM

SKU
: 27192

BRAND
: DIXON VALVE

MODEL
: 5500RK17

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	FKM-GFLT seals with PTFE U-cap kit for 5500G
Factory Part Number	5500RK17

** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us