# 5500-SERIES API COUPLER REPAIR KIT




** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 08:32 PM

SKU
: 27198

BRAND
: DIXON VALVE

MODEL
: 5500RK4

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

## TECHNICAL SPECIFICATIONS

| | |
|---|---|
| **Description** | Fluorosilicone complete seal kit for 5500F |
| **Factory Part Number** | 5500RK4 |
| **Weight Lb** | 0.5000 |



KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us