B5101 SERIES BUTTERFLY VALVE REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 01:44 AM

SKU
: 8176

BRAND
: DIXON VALVE

MODEL
: B5101-RKV150

Features:
(1) seat and (2) bushings included

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Color	Brown
Factory Part Number	B5101-RKV150
Material	FKM
Size	1-1/2"
Weight Lb	0.0900

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us