BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 12:55 AM

SKU
: 27439

BRAND
: DIXON VALVE

MODEL
: DBC62-150RK2

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement FKM seal cylinder, PTFE buttons and PTFE bushing (for DBC62-150)
Factory Part Number	DBC62-150RK2
Used on	1-1/2" Aluminum Couplers
Weight Lb	0.1800

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us