# BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT




** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 02:12 AM

SKU
: 27460

BRAND
: DIXON VALVE

MODEL
: DBCX1-200RK1

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

## TECHNICAL SPECIFICATIONS

| | |
|---|---|
| **Includes** | replacement seal kit, Buna crank shaft O-ring, PTFE stuffing box O-ring, Buna body O-ring, Buna cam gasket, PTFE O-ring (for DBC61-200) |
| **Factory Part Number** | DBCX1-200RK1 |
| **Used on** | 2" Aluminum Couplers, 2" Stainless Steel Couplers |
| **Weight Lb** | 0.0600 |



2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us