BAYLOC® DRY DISCONNECT COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 02:23 AM

SKU
: 27499

BRAND
: DIXON VALVE

MODEL
: DBCXX-300RK7

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Includes	replacement shaft kit, shaft, cotter pin, bearing, shaft retainer
Factory Part Number	DBCXX-300RK7
Used on	3" Aluminum Couplers, 3" Stainless Steel Couplers
Weight Lb	0.0100

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us