EZLINK® REPLACEMENT GASKET

DATE
: 11/23/2026 08:02 PM

SKU
: 23999

BRAND
: DIXON VALVE

MODEL
: EZL300-G-VI



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

Safety notes:
Take the seal out and check for any cracks, tears, nicks and make sure media is not trapped in the bellows area. If any damage to the seal, replace with a new Dixon® bellow seal that is compatible with the material that is to be conveyed.
The seal is marked with directional arrows and the word 'up' in 4 locations on the inside diameter indicating which way to insert it into the coupler. Arrows should point at you.
Warning! Only use EZLink™ seals for this coupling system. Traditional Cam & Groove gaskets, or other types of seals are not compatible and will fail.
If there is any question about which gasket to install, call Dixon® at 800-355-1991 for a recommendation.
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Material	FKM-A
Factory Part Number	EZL300-G-VI
Size	3"
Weight Lb	0.0790

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us