DIXON® VAPOR RECOVERY COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 01:21 AM

SKU
: 21712

BRAND
: DIXON VALVE

MODEL
: VR4040CSRK2

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Cam Arm Repair Kit: paddle arm and cam arm pin
Factory Part Number	VR4040CSRK2
Used on	VR4040CS-AL, VR4030CS-AL45, VR4040CS-AL45, VR4040CS-ALS45, VR4040CS-4MNPT, VR4030CS-SH
Weight Lb	0.0100

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us