
SEQUENTIAL VAPOR VENT REPAIR KIT



DATE
: 11/23/2026 08:41 PM

SKU
: 21739

BRAND
: DIXON VALVE

MODEL
: VR6030RK2

Features:
Piston, (2) top lip seal, bottom lip seal

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

TECHNICAL SPECIFICATIONS

Description	Replacement piston assembly
Factory Part Number	VR6030RK2
Used on	VR6030SQ sequential vapor vent
Weight Lb	0.0600

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us