# SEQUENTIAL VAPOR VENT REPAIR KIT




** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 10:14 PM

SKU
: 21745

BRAND
: DIXON VALVE

MODEL
: VR6035RK3

Features:
Baylast™ poppet gasket

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

## TECHNICAL SPECIFICATIONS

| | |
|---|---|
| **Description** | Replacement Baylast? Poppet Seal |
| **Factory Part Number** | VR6035RK3 |
| **Used on** | VR6035SQ sequential vapor vent |
| **Weight Lb** | 0.0100 |



2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us