SWING CHECK VALVE REPAIR KIT



FECHA
: 11/23/2026 09:30 PM

SKU
: 3500

MARCA
: DIXON VALVE

MODELO
: 3030RK3

Safety notes:
The smaller torsion springs will not return the flappers contained in the 4041RK1, 4041RK2, 4042RK1 and 4042RK2 kits to a fully closed position if the valve is mounted vertically or upside down. Ensure that these mounting positions are avoided if the smaller springs are used with the 4041RK1, 4041RK2, 4042RK1 and 4042RK2 kits.
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

ESPECIFICACIONES TÉCNICAS

Includes	Replacement left and right springs
Factory Part Number	3030RK3
Used on	3030 & 3090 series swing check valves, 4040RD and 4040TE
Weight Lb	0.0100

** Imágenes referenciales*
*** Algunas características pueden variar sin previo aviso, venta sujeta a stock disponible*

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us