API COUPLER REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/23/2026 06:05 PM

SKU
: 27155

BRAND
: DIXON VALVE

MODEL
: 5354K1

Features:
(2) O-rings 2-220 Buna, O-ring 2-212 Buna, shaft outside washer, shaft inside washer, shaft cotter pin
Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Buna shaft seal kit
Factory Part Number	5354K1
Used on	5300 & 5400 API couplers
Weight Lb	0.0320

KMX
2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us