# JRZL-100 SERIES POSITIVE DISPLACEMENT PUMP REPAIR KIT




** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 02:29 AM

SKU
: 18337

BRAND
: DIXON VALVE

MODEL
: RZL-115B-2E-EK

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

## TECHNICAL SPECIFICATIONS

| | |
|---|---|
| **Description** | Single Mechanical Seal Pump Elastomers |
| **Includes** | 2 - O-Ring, rotor bolt, EPDM, 2 - O-ring, rotor, EPDM, 2 - O-ring, rotor case, EPDM, 1 - O-ring, front cover, EPDM |
| **Mandatory Pkg/Box Qty** | 1 |
| **Material** | EPDM |
| **Factory Part Number** | RZL-115B-2E-EK |
| **Used on** | JRZL-100 Series |



2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us