JRZL-100 SERIES POSITIVE DISPLACEMENT PUMP REPAIR KIT

DATE
: 11/24/2026 01:50 AM

SKU
: 18346

BRAND
: DIXON VALVE

MODEL
: RZL-115B-4E-KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Double Mechanical Seal Repair Kit
Includes	2 - O-ring rotor EPDM, 4 - Seal Ring, 2 - O-ring, rotor case EPDM, 2 - O-ring, case, double seal EPDM, 2 - O-ring, shaft, double seal EPDM
Mandatory Pkg/Box Qty	1
Material	EPDM
Factory Part Number	RZL-115B-4E-KIT
Used on	JRZL-100 Series

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us