JRZL-400 SERIES POSITIVE DISPLACEMENT PUMP REPAIR KIT



** Referential image*
*** Some features may vary without prior notice. Sale subject to inventory availability*

DATE
: 11/24/2026 02:18 AM

SKU
: 18399

BRAND
: DIXON VALVE

MODEL
: RZL-440B-1V-KIT

Safety notes:
WARNING: Cancer and Reproductive Harm- www.P65Warnings.ca.gov

TECHNICAL SPECIFICATIONS

Description	Single O-ring Seal Repair Kit
Includes	2 - O-ring, rotor FKM, 2 - O-ring, rotor case FKM, 2 - Ceramic Coated Sleeve
Mandatory Pkg/Box Qty	1
Material	FKM
Factory Part Number	RZL-440B-1V-KIT
Used on	JRZL-400 Series

2645 Executive Park Drive, Weston, Fort Lauderdale, FL 33331, EEUU
sales@kmxusa.us
www.kmxusa.us